


VENTILATION AUDIT REPORT

SCHOOL:	Hillside Public School (2164)
AMU REGION:	Northern Sydney
STATE ELECTORATE:	Hawkesbury
LOCAL GOVERNMENT AREA:	The Hills

2164 - Hillside Public School
Site Plan (12647)













1:1,038

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Staff Room - (30.03 SQM)	 Office (7)	
B00A - R0005 - Clerical Office/Workroom - (11.85 SQM)	 Office (2)	
B00B - R0001 - Principal - (14.04 SQM)	 Office (3)	
B00B - R0004 - Movement - (6.68 SQM)	Not Applicable	Circulation or storage space.
B00B - R0005 - Home Base - (56.98 SQM) - Teaching Space: 1	 Student Space (26)	
B00G - R0002 - Practical Activities/Movement - 1hb - (19.36 SQM)	 Student Space (8)	
B00G - R0004 - Home Base - (58.76 SQM) - Teaching Space: 1	 Student Space (27)	
B00G - R0005 - Withdrawal Space - 2hb - (10.67 SQM)	 Student Space (4)	
B00G - R0006 - Home Base - (58.67 SQM) - Teaching Space: 1	 Student Space (27)	
B00G - R0008 - Practical Activities - 1hb - (19.36 SQM)	 Student Space (8)	
OS 505 10884 - OS 505 10884 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	