
VENTILATION AUDIT REPORT



SCHOOL:	Humula Public School (2188)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wagga Wagga
LOCAL GOVERNMENT AREA:	Wagga Wagga

2188 - Humula Public School Site Plan (12658)



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (43.61 SQM) - Teaching Space: 1	Student Space (20)	
B00A - R0003 - Reading Area - (43.34 SQM)	Student Space (20)	
B00A - R0004 - Principal - (11.11 SQM)	Office (2)	
B00A - R0005 - Movement - (27.77 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Entry Vestibule - (10.71 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Clerical Office/Workroom - (12.61 SQM)	Office (3)	
B00A - R0009 - Staff Room - (16.94 SQM)	Office (4)	
B00B - R0001 - Withdrawal Space - 1hb - (28.29 SQM)	Student Space (13)	
B00C - R0001 - Movement - (14.7 SQM)	Not Applicable	Circulation or storage space.