


VENTILATION AUDIT REPORT







SCHOOL:	Ilford Public School (2201)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Mid-Western

2201 - Ilford Public School
Site Plan (10416)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (53.37 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0004 - Special Programs Room - (8.18 SQM)	 Student Space (3)	
B00C - R0006 - Clerical Office/Workroom - (15.6 SQM)	 Office (3)	
B00C - R0007 - Principal - (13.18 SQM)	 Office (3)	
B00C - R0008 - Movement - (9.36 SQM)	Not Applicable	Circulation or storage space.
B00C - R0009 - Canteen - (10.49 SQM)	Not Applicable	Circulation or storage space.
B00C - R0013 - Movement - (15.45 SQM)	Not Applicable	Circulation or storage space.
B00C - R0014 - Reading Area - (30.4 SQM)	 Student Space (14)	
B00G - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (27)	