

VENTILATION AUDIT REPORT

SCHOOL:	Illabo Public School (2203)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Junee

2203 - Illabo Public School
Site Plan (10415)












1:596

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Duplicating Workroom - (11.11 SQM)	 Office (2)	
B00A - R0002 - Home Base - (43.95 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0003 - Home Base - (43.3 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0004 - Staff Room - (11.08 SQM)	 Office (2)	
B00A - R0005 - Movement - (33.45 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Home Base - (39.05 SQM) - Teaching Space: 1	 Student Space (18)	
B00C - R0003 - Practical Activities - 1hb - (10.43 SQM)	 Student Space (4)	
B00D - R0001 - Staff Room - (20.56 SQM)	 Office (5)	
B00F - R0001 - Special Programs Room - (51.1 SQM)	 Student Space (23)	
B00F - R0002 - Movement - (6.67 SQM)	Not Applicable	Circulation or storage space.
B00K - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	