


VENTILATION AUDIT REPORT



SCHOOL:	Illawarra Hospital School (5551)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wollongong
LOCAL GOVERNMENT AREA:	Wollongong

5551 - Illawarra Hospital School
Site Plan (12914)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R3001 - General Learning Space - (31.78 SQM) - Teaching Space: 1	 Student Space (14)	
B00A - R3002 - Staff Room Annexe - (12.75 SQM)	 Office (3)	