

# VENTILATION AUDIT REPORT

|                               |                             |
|-------------------------------|-----------------------------|
| <b>SCHOOL:</b>                | <b>Induna School (5756)</b> |
| <b>AMU REGION:</b>            | <b>North Coast</b>          |
| <b>STATE ELECTORATE:</b>      | <b>Clarence</b>             |
| <b>LOCAL GOVERNMENT AREA:</b> | <b>Clarence Valley</b>      |

Siteplan

## Ventilation Audit Key

| Category  | Description  |
|---|--|
|  | Category A<br>Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation.<br>NB. Circulation and storage areas should not be used for groups or gatherings.   |
|  | Category B<br>This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> .<br>The report details the number of people who can be accommodated safely in each of the identified spaces. |

