

VENTILATION AUDIT REPORT

SCHOOL:	Iona Public School (2211)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Port Stephens
LOCAL GOVERNMENT AREA:	Port Stephens

2211 - Iona Public School
Site Plan (12534)













1:883

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Home Base - (46.52 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0004 - Withdrawal Space - 1hb - (46.71 SQM)	 Student Space (21)	
B00B - R0001 - Outdoor Learning Area - (20.2 SQM)	Not Applicable	Circulation or storage space.
B00D - R0007 - Staff Room - (17.42 SQM)	 Office (4)	
B00D - R0008 - Principal Office - (11.26 SQM)	 Office (2)	
B00D - R0010 - Duplicating Workroom - (13.47 SQM)	 Office (3)	
B00D - R0018 - Clerical Office - (5.51 SQM)	 Office (1)	
B00D - R0021 - Reading Area - (45.85 SQM)	 Student Space (21)	
B00D - R0022 - Staff Kitchen - (22.9 SQM)	 Office (5)	
B00D - R0023 - Movement - (12.59 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Home Base - (60.9 SQM) - Teaching Space: 1	 Student Space (28)	
OS 602 10699 - OS 602 10699 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	