

VENTILATION AUDIT REPORT

SCHOOL:	Jerangle Public School (2225)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Monaro
LOCAL GOVERNMENT AREA:	Snowy Monaro

2225 - Jerangle Public School
Site Plan (13227)



1:562

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Clerical Office - (19.32 SQM)	 Office (4)	
B00A - R0003 - Reading Area - (35.9 SQM)	 Student Space (16)	
B00A - R0004 - Staff Room - (15.67 SQM)	 Office (3)	
B00D - R0003 - Home Base - (61.26 SQM)	 Student Space (28)	