


VENTILATION AUDIT REPORT

SCHOOL:	John Brotchie Nursery School (5423)
AMU REGION:	Sydney
STATE ELECTORATE:	Maroubra
LOCAL GOVERNMENT AREA:	Bayside

5423 - John Brotchie Nursery School
Site Plan (12553)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0006 - Home Base - Pre - (49.87 SQM) - Teaching Space: 1	● Student Space (23)	
B00A - R0007 - Withdrawal - Pre - (19.33 SQM)	● Student Space (8)	
B00A - R0009 - Movement - (13.66 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - Home Base - Pre - (109.16 SQM) - Teaching Space: 1	● Student Space (50)	
B00A - R0015 - Reading Area - (58.88 SQM)	● Student Space (27)	