

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Kangaloon Public School (2255)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Goulburn</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Wingecarribee</b>

2255 - Kangaloon Public School  
Site Plan (10447)














1:517

Printed: 20-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00G - R0002 - General Assistants - (7.05 SQM)	 Office (1)	
B00I - R0002 - Staff Room - (9.85 SQM)	 Office (2)	
B00I - R0004 - Home Base - (51.09 SQM) - Teaching Space: 1	 Student Space (23)	
B00L - R0003 - Movement - (8.84 SQM)	Not Applicable	Circulation or storage space.
B00L - R0009 - Staff Kitchen - (11.33 SQM)	 Office (2)	
B00L - R0010 - Reading Area - (13.5 SQM)	 Student Space (6)	
B00L - R0011 - Staff Room - (16.55 SQM)	 Office (4)	
B00L - R0014 - Seminar/Study - (14.53 SQM)	 Office (3)	
B00P - R0002 - Principal - (9.4 SQM)	 Office (2)	
B00P - R0003 - Home Base - (53.75 SQM) - Teaching Space: 1	 Student Space (24)	
B00P - R0004 - Clerical Office/Workroom - (26.15 SQM)	 Office (6)	
B00U - R0001 - Home Base - (58.31 SQM) - Teaching Space: 1	 Student Space (27)	