


VENTILATION AUDIT REPORT

SCHOOL:	Karangi Public School (2260)
AMU REGION:	North Coast
STATE ELECTORATE:	Coffs Harbour
LOCAL GOVERNMENT AREA:	Coffs Harbour

2260 - Karangi Public School
Site Plan (12961)



1:655

Printed: 19-Aug-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0012 - Staff Room - (34.4 SQM)	Office (8)	
B00A - R0013 - Staff Kitchen - (11.93 SQM)	Office (2)	
B00A - R0014 - Sick Bay - (7.42 SQM)	Student Space (3)	
B00A - R0015 - Entry Vestibule - (7.29 SQM)	Not Applicable	Circulation or storage space.
B00A - R0016 - Movement - (5.78 SQM)	Not Applicable	Circulation or storage space.
B00A - R0020 - Clerical Office - (23.67 SQM)	Office (5)	
B00A - R0021 - Movement - (10.16 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Withdrawal Space - 1hb - (12.99 SQM)	Student Space (6)	
B00C - R0003 - Home Base - (30.56 SQM)	Student Space (14)	
B00C - R0004 - Practical Activities - 1hb - (14.67 SQM)	Student Space (6)	
B00D - R0004 - Clerical Office - (11.92 SQM)	Office (2)	
B00D - R0006 - Staff Kitchen - (5.57 SQM)	Office (1)	
B00D - R0008 - Home Base - (76.54 SQM) - Teaching Space: 1	Student Space (35)	
B00I - R0001 - Reading Area - (91.74 SQM)	Student Space (42)	
B00J - R0002 - Canteen - (19.64 SQM)	Not Applicable	Circulation or storage space.
OS 602 10560 - OS 602 10560 - Learning Unit - Standard With P.A.A. - (76 SQM)	Student Space (35)	
OS 602 11617 - OS 602 11617 - Learning Unit - Standard With P.A.A. - (76 SQM)	Student Space (35)	