

VENTILATION AUDIT REPORT



SCHOOL:	Kirkton Public School (2314)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Singleton





Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (10.78 SQM)	Office (2)	
B00A - R0002 - Principal - (11.12 SQM)	Office (2)	
B00A - R0003 - Home Base - (43.86 SQM) - Teaching Space: 1	Student Space (20)	
B00A - R0004 - Reading Area - (43.93 SQM)	Student Space (20)	
B00A - R0005 - Staff Room - (11.09 SQM)	Office (2)	
B00A - R0006 - Movement - (21.75 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (45.71 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Home Base - (46.94 SQM) - Teaching Space: 1	Student Space (21)	
B00B - R0004 - Home Base - (47.53 SQM) - Teaching Space: 1	Student Space (22)	
B00G - R0002 - Practical Activities - 1hb - (19.68 SQM)	Student Space (9)	
B00G - R0003 - Home Base - (58.32 SQM) - Teaching Space: 1	Student Space (27)	
B00G - R0005 - Withdrawal Space - 2hb - (10.97 SQM)	Student Space (5)	
B00G - R0006 - Practical Activities - 1hb - (19.68 SQM)	Student Space (9)	
B00G - R0007 - Home Base - (58.31 SQM) - Teaching Space: 1	Student Space (27)	
B00I - R0002 - Entry Vestibule - (17.17 SQM)	Not Applicable	Circulation or storage space.
B00I - R0008 - Staff Kitchen - (5.33 SQM)	Office (1)	
B00I - R0009 - Staff Room - (17.91 SQM)	Office (4)	
B00I - R0012 - Clerical Office - (31.47 SQM)	Office (7)	
B00I - R0013 - Interview - (19.63 SQM)	Office (4)	
800I - R0014 - Principal - (14.92 SQM)	Office (3)	