
## **VENTILATION AUDIT REPORT**



SCHOOL:	Koorawatha Public School (2326)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Hilltops



## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
$\bigcirc$	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Withdrawal Space - 1hb - (23.82 SQM)	Student Space (11)	
B00A - R0004 - Staff Kitchen - (11.72 SQM)	Office (2)	
B00B - R0001 - Staff Room - (7.58 SQM)	Office (1)	
B00B - R0002 - Home Base - (60.29 SQM) - Teaching Space: 1	Student Space (27)	
B00B - R0003 - Reading Area - (47.5 SQM)	Student Space (22)	
B00B - R0006 - Movement - (12.35 SQM)	Not Applicable	Circulation or storage space.
B00B - R0007 - Movement - (12.57 SQM)	Not Applicable	Circulation or storage space.
B00C - R0004 - Home Base - (57.66 SQM) - Teaching Space: 1	Student Space (26)	
B00C - R0005 - Principal - (14.74 SQM)	Office (3)	
OS 505 13628 - OS 505 13628 - Admin Staff/Principal/Secure Store - (76 SQM)	Office (19)	