

# VENTILATION AUDIT REPORT













<b>SCHOOL:</b>	<b>Kulnura Public School (2334)</b>
<b>AMU REGION:</b>	<b>Hunter/Central Coast</b>
<b>STATE ELECTORATE:</b>	<b>Gosford</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Central Coast</b>

2334 - Kulnura Public School  
Site Plan (12598)



## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Home Base - (58.65 SQM) - Teaching Space: 1	 Student Space (27)	
B00A - R0006 - Withdrawal Space - 1hb - (6.6 SQM)	 Student Space (3)	
B00A - R0008 - Home Base - (58.65 SQM) - Teaching Space: 1	 Student Space (27)	
B00A - R0009 - Practical Activities - 1hb - (48.67 SQM)	 Student Space (22)	
B00B - R0002 - Practical Activities - 1hb - (15.66 SQM)	 Student Space (7)	
B00B - R0003 - Home Base - (62.52 SQM) - Teaching Space: 1	 Student Space (29)	
B00C - R0001 - Home Base - (67.34 SQM) - Teaching Space: 1	 Student Space (31)	
B00I - R0002 - Reading Area - (69.31 SQM)	 Student Space (32)	
B00I - R0006 - Practical Activities - 1hb - (16.02 SQM)	 Student Space (7)	
B00I - R0007 - Home Base - (63.81 SQM) - Teaching Space: 1	 Student Space (29)	
B00I - R0009 - Withdrawal Space - 1hb - (12.36 SQM)	 Student Space (5)	
OS 503 12521 - OS 503 12521 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	