

VENTILATION AUDIT REPORT









SCHOOL:	Ladysmith Public School (2353)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wagga Wagga
LOCAL GOVERNMENT AREA:	Wagga Wagga

2353 - Ladysmith Public School
Site Plan (13085)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (7.63 SQM)	 Office (1)	
B00A - R0002 - Home Base - (74.5 SQM) - Teaching Space: 1	 Student Space (34)	
B00A - R0006 - Duplicating Workroom - (11.01 SQM)	 Office (2)	
B00A - R0008 - Clerical Office - (9.57 SQM)	 Office (2)	
B00A - R0009 - Entry Vestibule - (5.17 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Practical Activities - 1hb - (23.82 SQM)	 Student Space (11)	
B00B - R0002 - Home Base - (33.4 SQM) - Teaching Space: 1	 Student Space (15)	
B00C - R0001 - Staff Room - (21.71 SQM)	 Office (5)	
B00H - R0001 - Reading Area - (59.85 SQM)	 Student Space (27)	