


VENTILATION AUDIT REPORT

SCHOOL:	Laguna Public School (2356)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Cessnock
LOCAL GOVERNMENT AREA:	Cessnock

2356 - Laguna Public School
Site Plan (12743)









1:568

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Entry Vestibule - (9.56 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Reading Area - (43.25 SQM)	 Student Space (20)	
B00C - R0002 - Special Programs Room - (45.85 SQM)	 Student Space (21)	
B00C - R0003 - Home Base - (64.34 SQM) - Teaching Space: 1	 Student Space (29)	
OS 505 10237 - OS 505 10237 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	
OS 602 15144 - OS 602 15144 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	
OS 602 15865 - OS 602 15865 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	