VENTILATION AUDIT REPORT

NSW Education | School Infrastructure

SCHOOL:	**Longneck Lagoon Environmental Education Centre (5690)**
AMU REGION:	**Western Sydney**
STATE ELECTORATE:	**Hawkesbury**
LOCAL GOVERNMENT AREA:	**Hawkesbury**

5690 - Longneck Lagoon Environmental Education Centre
Site Plan (13166)

0   80   160   240
Meters

1:5,304

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
●	Category A Operate this space in line with <u>COVID safe school operations</u>. It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
○	Category B This space should be occupied at 1 person per $4m^2$ to comply with <u>COVID safe school operations and the guided use of spaces</u>. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0007 - Movement - (10.61 SQM)	Not Applicable	Circulation or storage space.
B00B - R0005 - Movement - (8.81 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - General Learning Space - (52.86 SQM) - Teaching Space: 1	🔵 Student Space (24)	
B00C - R0002 - Canteen - (12.88 SQM)	Not Applicable	Circulation or storage space.
B00C - R0005 - Movement - (75.85 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - General Assistants - (29.47 SQM)	🔵 Office (7)	
OS 601 14378 - OS 601 14378 - Learning Unit - Standard/Withdrawal - (76 SQM)	🔵 Student Space (35)	