


VENTILATION AUDIT REPORT

SCHOOL:	Lyndhurst Public School (2436)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Blayney









2436 - Lyndhurst Public School
Site Plan (12776)



Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (39.04 SQM) - Teaching Space: 1	 Student Space (18)	
B00A - R0002 - Reading Area - (33.02 SQM)	 Student Space (15)	
B00A - R0004 - Staff Room Annexe - (12.96 SQM)	 Office (3)	
B00A - R0005 - Clerical Office - (5.53 SQM)	 Office (1)	
B00B - R0001 - Home Base - Bd/Cd/Ed - (29.3 SQM) - Teaching Space: 1	 Student Space (13)	
B00B - R0002 - Movement - (13.87 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Staff Kitchen - (8.37 SQM)	 Office (2)	
B00B - R0004 - Practical Activities - 1hb - (20.08 SQM)	 Student Space (9)	
B00F - R0001 - Reading Area - (59.89 SQM)	 Student Space (27)	