


VENTILATION AUDIT REPORT

SCHOOL:	Macdonald Valley Public School (2439)
AMU REGION:	Western Sydney
STATE ELECTORATE:	Hawkesbury
LOCAL GOVERNMENT AREA:	Hawkesbury

2439 - Macdonald Valley Public School
Site Plan (11184)



Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (11.6 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Home Base - (46.72 SQM) - Teaching Space: 1	● Student Space (21)	
B00A - R0003 - Withdrawal Space - 1hb - (12.67 SQM)	● Student Space (5)	
B00B - R0003 - Reading Area - (23.1 SQM)	● Student Space (10)	
B00G - R0002 - Communal Space - (59.59 SQM)	● Student Space (27)	
NS 020 13147 - NS 020 13147 - Staff Study/Store - (38 SQM)	Not Applicable	Circulation or storage space.