

VENTILATION AUDIT REPORT

SCHOOL:	Maimuru Public School (2448)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Hilltops

2448 - Maimuru Public School
Site Plan (10642)












1:790

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Withdrawal Space - 1hb - (11.88 SQM)	 Student Space (5)	
B00A - R0002 - Reading Area - (37.05 SQM)	 Student Space (17)	
B00A - R0003 - Home Base - (37.82 SQM) - Teaching Space: 1	 Student Space (17)	
B00A - R0005 - Principal - (11.99 SQM)	 Office (2)	
B00A - R0006 - Practical Activities - 1hb - (17.49 SQM)	 Student Space (8)	
B00D - R0005 - Special Programs Room - (38.82 SQM)	 Student Space (18)	
B00D - R0006 - Special Programs Room - (28.38 SQM)	 Student Space (13)	
B00H - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	
OS 500 18117 - OS 500 18117 - Admin - Library - (133 SQM)	 Office (33)	