
VENTILATION AUDIT REPORT



SCHOOL:	Main Arm Upper Public School (3236)
AMU REGION:	North Coast
STATE ELECTORATE:	Ballina
LOCAL GOVERNMENT AREA:	Byron





Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0009 - Home Base - (94.64 SQM) - Teaching Space: 1	Student Space (43)	
B00C - R0001 - Canteen - (35.08 SQM)	Not Applicable	Circulation or storage space.
B00C - R0004 - Canteen - (10.12 SQM)	Not Applicable	Circulation or storage space.
B00D - R0002 - Clerical Office - (19.12 SQM)	Office (4)	
B00D - R0004 - Clerical/Printing - (7.47 SQM)	Not Applicable	Circulation or storage space.
B00D - R0007 - Movement - (19.6 SQM)	Not Applicable	Circulation or storage space.
B00D - R0008 - Staff Room - (21.08 SQM)	Office (5)	
B00D - R0009 - Staff Kitchen - (5.65 SQM)	Office (1)	
B00D - R0011 - Principal - (17.22 SQM)	Office (4)	
B00D - R0012 - Reading Area - (72.14 SQM)	Student Space (33)	
B00E - R0004 - Staff Kitchen - (9.71 SQM)	Office (2)	
B00E - R0005 - Withdrawal Space - 1hb - (23.28 SQM)	Student Space (10)	
B00E - R0010 - Special Programs Room - (30.52 SQM)	Student Space (14)	
B00E - R0011 - Special Programs Room - (10.25 SQM)	Student Space (4)	
OS 601 10250 - OS 601 10250 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 602 14124 - OS 602 14124 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	
OS 602 16786 - OS 602 16786 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	