


VENTILATION AUDIT REPORT

SCHOOL:	Mallawa Public School (4262)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Moree Plains

4262 - Mallawa Public School
Site Plan (11834)




1:796

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R1001 - Movement - (23.2 SQM)	Not Applicable	Circulation or storage space.
B00A - R1008 - Home Base - (73.43 SQM) - Teaching Space: 1	 Student Space (34)	
B00D - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	
OS 500 10808 - OS 500 10808 - Admin - Library - (133 SQM)	 Office (33)	