


VENTILATION AUDIT REPORT

SCHOOL:	Manifold Public School (2464)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Richmond Valley

2464 - Manifold Public School
Site Plan (12453)




1:557

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (55.04 SQM) - Teaching Space: 1	 Student Space (25)	
B00F - R0001 - Home Base - (60.02 SQM) - Teaching Space: 1	 Student Space (27)	
OS 500 18113 - OS 500 18113 - Admin - Library - (133 SQM)	 Office (33)	