


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Marra Creek Public School (4454)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Barwon</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Warren</b>

4454 - Marra Creek Public School  
Site Plan (13088)



1:833

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (66.75 SQM) - Teaching Space: 1	● Student Space (30)	
B00B - R0001 - Movement - (27.28 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Movement - (20.54 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Reading Area - (29.14 SQM)	● Student Space (13)	
B00B - R0004 - Staff Room - (12.29 SQM)	● Office (3)	