


VENTILATION AUDIT REPORT

SCHOOL:	Marrar Public School (2485)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Coolamon

2485 - Marrar Public School
Site Plan (11441)







1:802

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0005 - Home Base - (43.76 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0011 - Home Base - (91 SQM) - Teaching Space: 1	 Student Space (42)	
B00F - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	
OS 500 18102 - OS 500 18102 - Admin - Library - (133 SQM)	 Office (33)	