


VENTILATION AUDIT REPORT

SCHOOL:	Martindale Public School (2492)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Muswellbrook

2492 - Martindale Public School
Site Plan (12802)










1:609

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Reading Area - (22.54 SQM)	 Student Space (10)	
B00A - R0002 - Home Base - (50.13 SQM) - Teaching Space: 1	 Student Space (23)	
B00A - R0003 - Movement - (5.69 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Withdrawal Space - 1hb - (5.64 SQM)	 Student Space (2)	
B00B - R0003 - Staff Room - (27.72 SQM)	 Office (6)	
B00D - R0001 - Communal Space - (64.95 SQM)	 Student Space (30)	
B00D - R0003 - Practical Activities - (5.65 SQM)	 Student Space (2)	
B00D - R0004 - Movement - (9.52 SQM)	Not Applicable	Circulation or storage space.
OS 531 12791 - OS 531 12791 - Library - (76 SQM)	 Student Space (35)	