

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Mathoura Public School (2500)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Murray</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Murray River</b>

2500 - Mathoura Public School  
Site Plan (10082)



1:840

Printed: 22-Jan-2021

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (58.74 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Home Base - (47.57 SQM) - Teaching Space: 1	● Student Space (22)	
B00A - R0004 - Home Base - (46.98 SQM) - Teaching Space: 1	● Student Space (21)	
B00B - R0001 - Movement - (56.29 SQM)	Not Applicable	Circulation or storage space.
B00B - R0004 - Movement - (6.14 SQM)	Not Applicable	Circulation or storage space.
B00B - R0005 - Withdrawal Space - 1hb - (12.75 SQM)	● Student Space (5)	
B00B - R0008 - Movement - (5.29 SQM)	Not Applicable	Circulation or storage space.
B00B - R0011 - Home Base - (56.34 SQM) - Teaching Space: 1	● Student Space (26)	
B00B - R0012 - Home Base - (85.25 SQM) - Teaching Space: 1	● Student Space (39)	
B00D - R0001 - Movement - (11.48 SQM)	Not Applicable	Circulation or storage space.
B00F - R0004 - Reading Area - (90.81 SQM)	● Student Space (42)	
OS 503 12446 - OS 503 12446 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	● Office (38)	