

VENTILATION AUDIT REPORT

SCHOOL:	Matong Public School (2501)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Coolamon

2501 - Matong Public School
Site Plan (12820)













1:951

Printed: 19-Aug-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (8.41 SQM)	 Office (2)	
B00A - R0004 - Withdrawal Space - 1hb - (11.01 SQM)	 Student Space (5)	
B00A - R0007 - Duplicating Workroom - (7.32 SQM)	 Office (1)	
B00A - R0009 - Movement - (28.26 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Home Base/Practical Activities - (88.88 SQM) - Teaching Space: 1	 Student Space (41)	
B00C - R0002 - Home Base - (42.02 SQM) - Teaching Space: 1	 Student Space (19)	
B00E - R0002 - Clerical Office/Workroom - (9.62 SQM)	 Office (2)	
B00E - R0003 - Movement - (14.15 SQM)	Not Applicable	Circulation or storage space.
B00E - R0004 - Sick Bay - (5.85 SQM)	 Student Space (2)	
B00E - R0006 - Principal - (16.35 SQM)	 Office (4)	
B00E - R0007 - Staff Room - (15.37 SQM)	 Office (3)	
B00J - R0002 - Home Base - (61.09 SQM) - Teaching Space: 1	 Student Space (28)	