

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Mayrung Public School (2508)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Murray</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Edward River</b>

2508 - Mayrung Public School  
Site Plan (10645)










1:609

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Withdrawal Space - 1hb - (7.08 SQM)	 Student Space (3)	
B00A - R0002 - Home Base - (53.36 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0004 - Principal - (8.84 SQM)	 Office (2)	
B00B - R0001 - Movement - (18.09 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Staff Room - (11.19 SQM)	 Office (2)	
B00D - R0002 - Home Base - (40.22 SQM) - Teaching Space: 1	 Student Space (18)	
B00E - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	
OS 505 10190 - OS 505 10190 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	