

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Meadow Flat Public School (2509)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Bathurst</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Lithgow</b>

2509 - Meadow Flat Public School  
Site Plan (12823)











1:672

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (10.93 SQM)	 Office (2)	
B00A - R0002 - Staff Room - (52.44 SQM)	 Office (13)	
B00A - R0003 - Movement - (5.2 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Canteen - (10.57 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Reading Area - (38.98 SQM)	 Student Space (18)	
B00E - R0001 - Practical Activities - 1hb - (13.05 SQM)	 Student Space (6)	
B00E - R0002 - Home Base - (39.89 SQM) - Teaching Space: 1	 Student Space (18)	
B00E - R0006 - Home Base - (53.4 SQM) - Teaching Space: 1	 Student Space (24)	
B00F - R0001 - Reading Area - (59.9 SQM)	 Student Space (27)	
OS 606 12019 - OS 606 12019 - Learning Unit - Standard With P.A.A A/C - (76 SQM)	 Student Space (35)	