


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Medlow Public School (2511)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Oxley</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Nambucca</b>

2511 - Medlow Public School  
Site Plan (11195)



1:733

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (33.09 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Staff Room - (15.51 SQM)	Office (3)	
B00A - R0004 - Home Base - (48.75 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0006 - Home Base - (53.29 SQM) - Teaching Space: 1	Student Space (24)	
B00D - R0002 - Reading Area - (44.72 SQM)	Student Space (20)	
B00D - R0005 - Movement - (11.52 SQM)	Not Applicable	Circulation or storage space.
B00F - R0002 - Clerical Office - (15.73 SQM)	Office (3)	
B00F - R0005 - Principal - (10.52 SQM)	Office (2)	
B00F - R0006 - Movement - (5.11 SQM)	Not Applicable	Circulation or storage space.
B00F - R0008 - Staff Room - (30.39 SQM)	Office (7)	
B00F - R0009 - Staff Room Annexe - (7.61 SQM)	Office (1)	
B00F - R0010 - Canteen - (10.39 SQM)	Not Applicable	Circulation or storage space.
B00F - R0014 - Movement - (15.85 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Communal Space - (59.97 SQM)	Student Space (27)	