


VENTILATION AUDIT REPORT





SCHOOL:	Megalong Public School (2515)
AMU REGION:	Western Sydney
STATE ELECTORATE:	Blue Mountains
LOCAL GOVERNMENT AREA:	Blue Mountains

2515 - Megalong Public School
Site Plan (10476)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Reading Area - (20.75 SQM)	 Student Space (9)	
B00A - R0004 - Clerical Office/Workroom - (18.65 SQM)	 Office (4)	
B00B - R0001 - Movement - (14.89 SQM)	Not Applicable	Circulation or storage space.
OS 602 14839 - OS 602 14839 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	
OS 750 16842 - OS 750 16842 - Learning Unit - ESL - (38 SQM)	 Student Space (17)	