
VENTILATION AUDIT REPORT



SCHOOL:	Mian School (5577)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Dubbo
LOCAL GOVERNMENT AREA:	Dubbo

5577 - Mian School Site Plan (13315)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00H - R0020 - Entry Vestibule - (37.91 SQM)	Not Applicable	Circulation or storage space.
B00H - R0021 - Staff Study - (44.47 SQM)	Office (11)	
B00H - R0023 - Deputy Principal - (12.39 SQM)	Office (3)	
B00H - R0024 - Principal - (13.08 SQM)	Office (3)	
B00H - R0025 - Interview - (13.31 SQM)	Office (3)	
B00H - R0026 - Clerical Office - (28.16 SQM)	Office (7)	
B00H - R0027 - Home Base - (60.09 SQM) - Teaching Space: 1	Student Space (27)	
B00H - R0030 - Home Base - (55.53 SQM) - Teaching Space: 1	Student Space (25)	
B00H - R0032 - Home Base - (50.35 SQM) - Teaching Space: 1	Student Space (23)	
B00H - R0033 - Home Base - (51.17 SQM) - Teaching Space: 1	Student Space (23)	
B00H - R0034 - Staff Kitchen - (13.32 SQM)	Office (3)	
B00H - R0035 - Movement - (36.87 SQM)	Not Applicable	Circulation or storage space.
B00H - R0036 - Sick Bay - (9.39 SQM)	Student Space (4)	
B00H - R0038 - Movement - (5.46 SQM)	Not Applicable	Circulation or storage space.
B00H - R0040 - Staff Room - (21.66 SQM)	Office (5)	
B00J - R0001 - Reading Area - (59.93 SQM)	Student Space (27)	