


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Milbrodale Public School (2550)</b>
<b>AMU REGION:</b>	<b>Hunter/Central Coast</b>
<b>STATE ELECTORATE:</b>	<b>Cessnock</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Singleton</b>

2550 - Milbrodale Public School  
Site Plan (11203)










1:1,033

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Practical Activities - 1hb - (24.38 SQM)	 Student Space (11)	
B00A - R0002 - Home Base - (51.13 SQM) - Teaching Space: 1	 Student Space (23)	
B00A - R0003 - Withdrawal Space - 1hb - (14.72 SQM)	 Student Space (6)	
B00B - R0002 - Clerical Office - (10.7 SQM)	 Office (2)	
B00B - R0003 - Principal - (10.34 SQM)	 Office (2)	
B00B - R0005 - Entry Vestibule - (9.98 SQM)	Not Applicable	Circulation or storage space.
B00B - R0007 - Reading Area - (35.99 SQM)	 Student Space (16)	
B00E - R0001 - Canteen - (9.77 SQM)	Not Applicable	Circulation or storage space.
B00G - R0002 - Reading Area - (64.44 SQM)	 Student Space (29)	