
VENTILATION AUDIT REPORT



SCHOOL:	Millers Forest Public School (2554)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Maitland
LOCAL GOVERNMENT AREA:	Maitland





Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (53.77 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R0003 - Movement - (8.63 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Staff Room - (19.47 SQM)	Office (4)	
B00B - R0002 - Practical Activities - 1hb - (9.89 SQM)	Student Space (4)	
B00B - R0003 - Special Programs Room - (7.56 SQM)	Student Space (3)	
B00B - R0005 - Principal - (14.95 SQM)	Office (3)	
B00B - R0006 - Clerical Office - (12.11 SQM)	Office (3)	
B00B - R0008 - Movement - (7.46 SQM)	Not Applicable	Circulation or storage space.
B00B - R0009 - Movement - (22.17 SQM)	Not Applicable	Circulation or storage space.
B00B - R0010 - Home Base - (53.56 SQM) - Teaching Space: 1	Student Space (24)	
B00B - R0011 - Movement - (13.63 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Reading Area - (17.58 SQM)	Student Space (8)	
B00D - R0003 - Practical Activities - (6.23 SQM)	Student Space (2)	
OS 602 13316 - OS 602 13316 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	