

VENTILATION AUDIT REPORT

| | |
|-------------------------------|--------------------------------------|
| SCHOOL: | Mingoola Public School (4115) |
| AMU REGION: | North Western NSW |
| STATE ELECTORATE: | Lismore |
| LOCAL GOVERNMENT AREA: | Tenterfield |

4115 - Mingoola Public School
Site Plan (11442)



1:535

Printed: 21-Mar-2020

Ventilation Audit Key

| Category | Description |
|---|--|
|  | Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings. |
|  | Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces. |

| Entity Location | Audit Condition Classification (Capacity) | Comment |
|--|---|-------------------------------|
| B00A - R0001 - Movement - (13.61 SQM) | Not Applicable | Circulation or storage space. |
| B00A - R0002 - Clerical Office/Workroom - (7.65 SQM) | Office (1) | |
| B00A - R0003 - Staff Room - (9.87 SQM) | Office (2) | |
| B00A - R0005 - Home Base - (53.72 SQM) | Student Space (24) | |
| B00B - R0003 - Principal - (8.55 SQM) | Office (2) | |
| B00B - R0004 - Reading Area - (39.07 SQM) | Student Space (18) | |
| B00G - R0001 - Communal Space - (60.87 SQM) | Student Space (28) | |
| B00I - R0001 - Practical Activities - (34.13 SQM) | Student Space (15) | |