
VENTILATION AUDIT REPORT



SCHOOL:	Mitchells Island Public School (2580)
AMU REGION:	North Coast
STATE ELECTORATE:	Myall Lakes
LOCAL GOVERNMENT AREA:	Mid-Coast

2580 - Mitchells Island Public School Site Plan (11443)



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Clerical/Printing - (10.64 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Home Base - (47.02 SQM) - Teaching Space: 1	Student Space (21)	
B00A - R0005 - Home Base - (47.62 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0007 - Duplicating Workroom - (8.86 SQM)	Office (2)	
B00B - R0002 - Staff Room - (22.62 SQM)	Office (5)	
B00B - R0003 - Staff Kitchen - (6.92 SQM)	Office (1)	
B00F - R0007 - Special Programs Room - (14.49 SQM)	Student Space (6)	
B00F - R0008 - Reading Area - (29.2 SQM)	Student Space (13)	
B00F - R0010 - Staff Kitchen - (10.39 SQM)	Office (2)	
B00F - R0015 - Principal - (9.56 SQM)	Office (2)	
B00F - R0016 - Clerical Office - (11.71 SQM)	Office (2)	
B00H - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	Student Space (27)	