


VENTILATION AUDIT REPORT

SCHOOL:	Monteagle Public School (2599)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Hilltops

2599 - Monteagle Public School
Site Plan (12926)












1:1,164

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room - (26.02 SQM)	 Office (6)	
B00A - R0005 - Entry Vestibule - (8.07 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Clerical Office - (10.6 SQM)	 Office (2)	
B00A - R0008 - Principal - (13.77 SQM)	 Office (3)	
B00B - R0002 - Practical Activities - 1hb - (18.96 SQM)	 Student Space (8)	
B00B - R0004 - Home Base - (47.52 SQM) - Teaching Space: 1	 Student Space (22)	
B00B - R0007 - Movement - (14.55 SQM)	Not Applicable	Circulation or storage space.
B00B - R0008 - Home Base - (51.27 SQM) - Teaching Space: 1	 Student Space (23)	
B00D - R0003 - Home Base - (42.47 SQM) - Teaching Space: 1	 Student Space (19)	
B00E - R0001 - Home Base/Practical Activities - (45.43 SQM) - Teaching Space: 1	 Student Space (21)	
B00F - R0001 - Canteen - (23.5 SQM)	Not Applicable	Circulation or storage space.
B00I - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	