













VENTILATION AUDIT REPORT

SCHOOL:	Mount Druitt Tutorial Centre (879)
AMU REGION:	Western Sydney
STATE ELECTORATE:	
LOCAL GOVERNMENT AREA:	

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0006 - Practical Activities - (6.96 SQM)	 Student Space (3)	
B00B - R0007 - Home Base - (47.35 SQM)	 Student Space (21)	
B00B - R0008 - Home Base - (47.58 SQM)	 Student Space (22)	
B00B - R0009 - Practical Activities - (6.96 SQM)	 Student Space (3)	
B00B - R0021 - Craft Room - (88.26 SQM)	 Office (22)	
B00B - R0025 - Home Base - (54 SQM)	 Student Space (25)	
B00B - R0026 - Home Base - (53.93 SQM)	 Student Space (25)	
B00B - R0028 - Movement - (278.26 SQM)	Not Applicable	Circulation or storage space.
B00B - R0036 - Administration - Clerical - (19.84 SQM)	 Office (4)	
B00B - R0037 - Staff Kitchen - (7.15 SQM)	 Office (1)	
B00B - R0042 - Commonroom - (31.34 SQM)	 Office (7)	
B00B - R0043 - Independent Learning Space - (59.22 SQM)	 Student Space (27)	
B00B - R0044 - Practical Activities - (5.37 SQM)	 Student Space (2)	