


VENTILATION AUDIT REPORT

SCHOOL:	Mount Pleasant Public School (2647)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Singleton

2647 - Mount Pleasant Public School
Site Plan (12948)















1:558

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Staff Room - (15.92 SQM)	 Office (3)	
B00A - R0004 - Practical Activities - 1hb - (14.44 SQM)	 Student Space (6)	
B00A - R0005 - Home Base - (57.9 SQM) - Teaching Space: 1	 Student Space (26)	
B00D - R0001 - Reading Area - (44.84 SQM)	 Student Space (20)	
B00G - R0005 - Staff Kitchen - (13.65 SQM)	 Office (3)	
B00G - R0009 - Home Base - (65.74 SQM) - Teaching Space: 1	 Student Space (30)	
B00G - R0013 - Practical Activities - 1hb - (19.82 SQM)	 Student Space (9)	
B00I - R0002 - Reading Area - (69.31 SQM)	 Student Space (32)	
B00I - R0006 - Practical Activities - 1hb - (18.33 SQM)	 Student Space (8)	
B00I - R0007 - Home Base - (61.52 SQM) - Teaching Space: 1	 Student Space (28)	
B00I - R0009 - Withdrawal Space - 1hb - (12.19 SQM)	 Student Space (5)	
OS 750 11795 - OS 750 11795 - Learning Unit - ESL - (38 SQM)	 Student Space (17)	