


VENTILATION AUDIT REPORT

SCHOOL:	Mullaley Public School (2660)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Gunnedah

2660 - Mullaley Public School
Site Plan (10658)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Movement - (10.08 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Withdrawal Space - 1hb - (25.81 SQM)	● Student Space (11)	
B00A - R0005 - Principal - (8.84 SQM)	● Office (2)	
B00B - R0002 - Home Base - (39.68 SQM) - Teaching Space: 1	● Student Space (18)	
B00B - R0003 - Movement - (14.18 SQM)	Not Applicable	Circulation or storage space.
B00B - R0004 - Practical Activities - 1hb - (13.03 SQM)	● Student Space (6)	
B00C - R0001 - Movement - (22.49 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Home Base - (48.64 SQM) - Teaching Space: 1	● Student Space (22)	
B00C - R0006 - Staff Room - (11.16 SQM)	● Office (2)	
B00D - R0001 - Movement - (24.15 SQM)	Not Applicable	Circulation or storage space.
B00D - R0004 - Home Base - (48.58 SQM) - Teaching Space: 1	● Student Space (22)	
B00D - R0007 - Clerical/Printing - (22.24 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Outdoor Learning Area - (18.48 SQM)	Not Applicable	Circulation or storage space.