


VENTILATION AUDIT REPORT










SCHOOL:	Mumbil Public School (2669)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Dubbo
LOCAL GOVERNMENT AREA:	Dubbo

2669 - Mumbil Public School
Site Plan (13562)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room - (13.92 SQM)	 Office (3)	
B00A - R0002 - Home Base - (71.47 SQM) - Teaching Space: 1	 Student Space (33)	
B00A - R0003 - Withdrawal Space - 1hb - (35.24 SQM)	 Student Space (16)	
B00A - R0004 - Home Base - (53 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0006 - Clerical Office - (16.63 SQM)	 Office (4)	
B00A - R0008 - Movement - (18.89 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Movement - (29.2 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Special Programs Room - (43.92 SQM)	 Student Space (20)	
B00D - R0001 - Reading Area - (30.72 SQM)	 Student Space (14)	
B00D - R0002 - Staff Room - (8.13 SQM)	 Office (2)	
B00G - R0001 - Reading Area - (59.92 SQM)	 Student Space (27)	