


VENTILATION AUDIT REPORT

SCHOOL:	Nangus Public School (2699)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Cootamundra-Gundagai

2699 - Nangus Public School
Site Plan (11846)











1:1,107

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (49.45 SQM) - Teaching Space: 1	 Student Space (22)	
B00A - R0003 - Reading Area - (34.74 SQM)	 Student Space (16)	
B00A - R0006 - Principal - (8.82 SQM)	 Office (2)	
B00A - R0008 - Special Programs Room - (10.58 SQM)	 Student Space (4)	
B00A - R0009 - Home Base - (50.43 SQM) - Teaching Space: 1	 Student Space (23)	
B00A - R0010 - Movement - (7.96 SQM)	Not Applicable	Circulation or storage space.
B00A - R0012 - Entry Vestibule - (8.44 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - Principal - (8.88 SQM)	 Office (2)	
B00C - R0002 - Staff Room - (20.43 SQM)	 Office (5)	
B00F - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	