


VENTILATION AUDIT REPORT

SCHOOL:	Niangala Public School (2748)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth

2748 - Niangala Public School
Site Plan (11222)










1:555

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Staff Room - (13.98 SQM)	 Office (3)	
B00A - R0004 - Reading Area - (51.76 SQM)	 Student Space (24)	
B00A - R0005 - Duplicating Workroom - (8.76 SQM)	 Office (2)	
B00A - R0006 - Principal - (12.83 SQM)	 Office (3)	
B00A - R0007 - Clerical Office - (10.86 SQM)	 Office (2)	
B00F - R0001 - Movement - (22.39 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	
OS 601 10714 - OS 601 10714 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	