
VENTILATION AUDIT REPORT



SCHOOL:	Nillo Infants School (5128)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Maitland
LOCAL GOVERNMENT AREA:	Maitland



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Home Base - (47.64 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0005 - Home Base - (47.66 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0006 - Duplicating Workroom - (9.71 SQM)	Office (2)	
B00A - R0007 - Principal - (13.54 SQM)	Office (3)	
B00A - R0011 - Movement - (5.59 SQM)	Not Applicable	Circulation or storage space.
B00A - R0015 - Clerical Office - (19 SQM)	Office (4)	
B00A - R0016 - Movement - (30.3 SQM)	Not Applicable	Circulation or storage space.
B00A - R0021 - Staff Room - (17.57 SQM)	Office (4)	
B00A - R0022 - Staff Kitchen - (9.56 SQM)	Office (2)	
B00B - R0002 - Reading Area - (46.77 SQM)	Student Space (21)	
B00B - R0003 - Practical Activities - 1hb - (9.18 SQM)	Student Space (4)	
B00J - R0002 - Practical Activities - 1hb - (21.63 SQM)	Student Space (10)	
B00J - R0004 - Home Base - (63.41 SQM) - Teaching Space: 1	Student Space (29)	
B00J - R0005 - Withdrawal Space - 2hb - (10.84 SQM)	Student Space (5)	
B00J - R0006 - Home Base - (63.41 SQM) - Teaching Space: 1	Student Space (29)	
B00J - R0008 - Practical Activities - 1hb - (21.63 SQM)	Student Space (10)	