

VENTILATION AUDIT REPORT

SCHOOL:	Nowendoc Public School (2768)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Walcha

2768 - Nowendoc Public School
Site Plan (11223)












1:680

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (9.37 SQM)	 Office (2)	
B00A - R0003 - Withdrawal Space - 1hb - (19.23 SQM)	 Student Space (8)	
B00A - R0004 - Principal - (11.32 SQM)	 Office (2)	
B00A - R0005 - Home Base - (54.02 SQM)	 Student Space (25)	
B00A - R0007 - Home Base - (56.22 SQM)	 Student Space (26)	
B00A - R0009 - Staff Kitchen - (6.62 SQM)	 Office (1)	
B00A - R0011 - Movement - (30.11 SQM)	Not Applicable	Circulation or storage space.
B00A - R0012 - Entry Vestibule - (9.81 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Reading Area - (31.23 SQM)	 Student Space (14)	
B00D - R0001 - Special Programs Room - (26.39 SQM)	 Student Space (12)	
B00F - R0001 - Reading Area - (59.95 SQM)	 Student Space (27)	