

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Observatory Hill Environmental Education Centre (5745)</b>
<b>AMU REGION:</b>	<b>Sydney</b>
<b>STATE ELECTORATE:</b>	<b>Sydney</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Sydney</b>

5745 - Observatory Hill Environmental Education Centre  
Site Plan (14581)








1:281

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0003 - Interview - (13.63 SQM)	 Office (3)	
B00B - R0006 - Duplicating Workroom - (6.46 SQM)	 Office (1)	
B00B - R0008 - Movement - (25.63 SQM)	Not Applicable	Circulation or storage space.
B00B - R0010 - Seminar/Study - (17.53 SQM)	 Office (4)	
B00B - R0012 - Movement - (32.82 SQM)	Not Applicable	Circulation or storage space.
B00B - R0016 - Staff Room - (37.28 SQM)	 Office (9)	
B00B - R0019 - Home Base - (75.99 SQM) - Teaching Space: 1	 Student Space (35)	