


VENTILATION AUDIT REPORT

SCHOOL:	Old Bonalbo Public School (2800)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Kyogle

2800 - Old Bonalbo Public School
Site Plan (10502)










1:677

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (11.76 SQM)	 Office (2)	
B00A - R0002 - Clerical Office - (11.76 SQM)	 Office (2)	
B00A - R0004 - Home Base - (44.56 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0012 - Clerical Office - (16.72 SQM)	 Office (4)	
B00A - R0013 - Staff Room - (22.24 SQM)	 Office (5)	
B00A - R0014 - Movement - (34.46 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (15.79 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Home Base - (44.11 SQM) - Teaching Space: 1	 Student Space (20)	
B00H - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (27)	