


VENTILATION AUDIT REPORT

SCHOOL:	Palm Avenue School (5650)
AMU REGION:	Western Sydney
STATE ELECTORATE:	Seven Hills
LOCAL GOVERNMENT AREA:	Parramatta














5650 - Palm Avenue School
Site Plan (12809)



Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (20.71 SQM)	 Office (5)	
B00A - R0002 - Deputy Principal - (14.9 SQM)	 Office (3)	
B00A - R0003 - Movement - (25.14 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Clerical Office - (14.98 SQM)	 Office (3)	
B00A - R0005 - Duplicating Workroom - (11.51 SQM)	 Office (2)	
B00A - R0006 - Interview - (15.54 SQM)	 Office (3)	
B00A - R0011 - Movement - (7.77 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - Interview - (7.18 SQM)	 Office (1)	
B00A - R0014 - Interview - (7.61 SQM)	 Office (1)	
B00A - R0015 - Staff Room - (49.24 SQM)	 Office (12)	
B00A - R0016 - Staff Kitchen - (5.64 SQM)	 Office (1)	
B00A - R0018 - Movement - (7.88 SQM)	Not Applicable	Circulation or storage space.
B00A - R0019 - Clerical Office - (9.42 SQM)	 Office (2)	
B00A - R0020 - Clerical Office - (10.93 SQM)	 Office (2)	
B00A - R0021 - Clerical Office - (6.2 SQM)	 Office (1)	
OS 501 15190 - OS 501 15190 - Admin Staff/Principal/Deputy/Dup/Clinic - (209 SQM)	 Office (52)	