

VENTILATION AUDIT REPORT

SCHOOL:	Palmers Island Public School (2829)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Clarence Valley









2829 - Palmers Island Public School
Site Plan (10674)



Printed: 10-Jul-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Canteen - (10.93 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Reading Area - (89.03 SQM)	 Student Space (41)	
B00B - R0004 - Staff Room - (44.2 SQM)	 Office (11)	
B00F - R0002 - Practical Activities - 1hb - (19.62 SQM)	 Student Space (9)	
B00F - R0004 - Home Base - (59.73 SQM) - Teaching Space: 1	 Student Space (27)	
B00F - R0005 - Withdrawal Space - 2hb - (11.67 SQM)	 Student Space (5)	
B00F - R0006 - Home Base - (59.44 SQM) - Teaching Space: 1	 Student Space (27)	
B00F - R0008 - Practical Activities - 1hb - (19.72 SQM)	 Student Space (9)	
OS 500 18127 - OS 500 18127 - Admin - Library - (133 SQM)	 Office (33)	